

Req/Changes Project ID: 124 Project Description: St. Bonaventure Church Multipurpose Bldg & HOPE Exp
 JOB ID: 1032 Job Description: St. Bonaventure Church - Multipurpose Bldg. & HOPE Expansion

96 CLO (Closed) 5 OUT (Outstanding) 2 VOID (VOID)

	ID:	id	Rev	Job	status:	RE:	Date Issued:	to recipient:	to company:	Req'd Date:	Initiated By	Ref. #	Desc.	method:	File Location:	from co:	signed_by:	# of pages	F ▲
	105	1854		1032			10/21/2008	Luis Barrios, Jr	DDWA							SNYDER			
		104		1853			10/21/2008	Luis Barrios, Jr	DDWA							SNYDER			
		103		1624	OUT	Mailbox @ gate	4/3/2006	Luis Barrios, Jr	DDWA	4/5/2006	SNYDER LANG		Please provide Sny			SNYDER	Mel Lopez	1	
		102		1599	OUT	Revised Footing for Gate & Fence	3/30/2006	Luis Barrios, Jr	DDWA	3/31/2006	SNYDER LANG		Per the walk thru @			SNYDER	Mel Lopez	1	
		101		1481	OUT	Chain link fence gate post anchors	3/15/2006	Luis Barrios, Jr	DDWA	3/15/2006	SNYDER LANG		Please confirm that			SNYDER	Marivic S. Ha	1	
		100		1446	CLO	Stainless Steel around Roll-up door	3/3/2006	Luis Barrios, Jr	DDWA	3/5/2006	SNYDER LANG		Per DC #40, please			SNYDER	Marivic S. Ha	1	
		99		1436	OUT	Planter along Northwest wall by Lobby 108	3/1/2006	Daniel D. White	DDWA	3/2/2006	ST. BONAVENTURE		Sheet A.1.2 indicate			SNYDER	Marivic S. Ha	1	
		98		1426	CLO	Revisions to Door 13, 15, 19 & 20	2/23/2006	Luis Barrios, Jr	DDWA	2/24/2006	ST. BONAVENTURE		Per Linda's request			SNYDER	Marivic S. Ha	1	
		97		1422	CLO	Ceiling Fan & Projection Screen	2/23/2006	Luis Barrios, Jr	DDWA	2/23/2006	SNYDER LANG		Please provide loca			SNYDER	Marivic S. Ha		
		96		1421	CLO	Signage Requirements	2/23/2006	Luis Barrios, Jr	DDWA	2/24/2005	SNYDER LANG		SL's scope for sign			SNYDER	Marivic S. Ha	1	
		95		1411	CLO	Ceramic Tile & Carpet Transition at Reception	2/17/2006	Luis Barrios, Jr	DDWA	2/20/2006	SNYDER LANG		Please provide layo			SNYDER	Marivic S. Ha	1	
		94		1410	OUT	Keying for cabinet and drawer locks	2/17/2006	Luis Barrios, Jr	DDWA	2/20/2006	TAHITI CABINET		Please provide key			SNYDER	Marivic S. Ha	1	
		93		1408	CLO	Light Fixture in Room 113	2/15/2006	Luis Barrios, Jr	DDWA	2/16/2006	SNYDER LANG		Room 113 is not w			SNYDER	Marivic S. Ha	1	
		92		1388	CLO	Lights in Room 108 & 109	2/15/2006	Daniel D. White	DDWA	2/16/2006	DDWA		Per our previous ci			SNYDER	Marivic S. Ha	1	
		91		1387	CLO	2" CW Connection	2/7/2006	Daniel D. White	DDWA	2/9/2006	SNYDER LANG		Per our meeting on			SNYDER	Marivic S. Ha	1	
		90		1385	CLO	Lighting Override Switch Location @ MP Bldg	2/3/2006	Luis Barrios, Jr	DDWA	2/6/2006	SNYDER LANG		Please provide loca			SNYDER	Melissa Lade	1	
		89		1384	CLO	Timer/Shut-Off Switch for Exterior Lights @ H	2/3/2006	Luis Barrios, Jr	DDWA	2/6/2006	SNYDER LANG		There is no timer/sl			SNYDER	Melissa Lade		
		88		1339	CLO	Flooring Finish Requirements in HOPE Room 10	1/23/2006	Luis Barrios, Jr	DDWA	1/24/2006	SNYDER LANG		Per A2.1, the floori			SNYDER	Melissa Lade		
		87		1332	CLO	Electrical Trim Color/Style Confirmation @ HOP	1/19/2006	Luis Barrios, Jr	DDWA	1/20/2006	SNYDER LANG		Please confirm that			SNYDER	Melissa Lade		
		86		1316	CLO	Irrigation Control Panel Location Elevation	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANG		Please Provide Loc			SNYDER	Melissa Lade		
		85		1315	CLO	Elevation for Retaining Wall @ northeast corne	1/18/2006	Luis Barrios, Jr	DDWA	1/25/2006	SNYDER LANG		Please provide Elev			SNYDER	Marivic S. Ha	1	
		84		1314	CLO	Retaining Wall Elevation @ northwest corner c	1/17/2006	Luis Barrios, Jr	DDWA	1/25/2006	SNYDER LANG		Please provide Elev			SNYDER	Melissa Lade	1	
		83		1313	CLO	Gate/Fence @ SE corner between MP Bldg & I	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANG		Insufficient informa			SNYDER	Melissa Lade	1	
		82		1312	CLO	Gate/Fence @ NW corner between MP Bldg &	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANG		Please provide nec			SNYDER	Melissa Lade	1	
Cost Documents		81		1311	CLO	Exterior Paint Colors for HOPE & Multipurpose	1/13/2006	Luis Barrios, Jr	DDWA	1/13/2006	SNYDER LANG		Please provide pair			SNYDER	Melissa Lade	1	
Correspondence		80		1202	CLO	Ceramic Tile behind Mirrors in Bathrooms 103,	12/28/2005	Luis Barrios, Jr	DDWA	12/29/2005	COASTAL TILE		Sheet A5.2 does n			SNYDER	Melissa Lade		
Miscellaneous		79		1199	CLO	Telephone/Computer Data Outlet Locations in I	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	SNYDER LANG		Sheet E2.4 specifi			SNYDER	Melissa Lade		
		78		1198	CLO	Electrical Outlet Required in HOPE Expansion E	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	SNYDER LANG		Per City of Huntingt			SNYDER	Melissa Lade		
		77		1197	CLO	Band Detail at Line D to Cover Bolts	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	AMORT CONS		Please provide deta			SNYDER	Melissa Lade		
		76	A	1196	CLO	Soffit Framing Detail at Accordion Partition	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	AMORT CONS		Please provide deta			SNYDER	Melissa Lade		
		75	A	1195	CLO	Carpeting - Confirmation of DDWA Bulletin #11	12/22/2005	Luis Barrios, Jr	DDWA	12/22/2005	SNYDER LANG		This is a confirming			SNYDER	Melissa Lade		
		74		1194	CLO	Millwork Size Verification for File Cabinet & Kit	12/22/2005	Luis Barrios, Jr	DDWA	12/23/2005	TAHITI CABINET		Please verify the fi			SNYDER	Melissa Lade		
		73		1189	CLO	Restroom 103 & 104 - revised wall tile design	12/20/2005	Luis Barrios, Jr	DDWA	12/20/2005	COASTAL TILE		Per DDWA DC 42 (SNYDER	Marivic S. Ha	1	
		72	A	1188	CLO	HOPE Restroom #105	12/20/2005	Luis Barrios, Jr	DDWA	12/20/2005	SNYDER LANG		Per the DDWA DC ;			SNYDER	Marivic S. Ha	2	
		71		1170	CLO	Layout for Light Fixture types K & L in Multipur	12/12/2005	Luis Barrios, Jr	DDWA	12/13/2005	SNYDER LANG		Please provide a la			SNYDER	Will Scott		
		70		1168	CLO	Hose Bibb HB-1	12/12/2005	Marivic S. Ha	SNYDER LANG	12/12/2005	ACADEMY ME		Please clarify type			SNYDER	Marivic S. Ha	2	
		69		1162	CLO	Plaster Expansion Joint @ Multipurpose Bldg. -	12/12/2005	Luis Barrios, Jr	DDWA	12/13/2005	SNYDER LANG		6/A2.3 calls for Pla			SNYDER	Will Scott		
		68	B	1161	CLO	Relocation of EF-4	12/9/2005	Luis Barrios, Jr	DDWA	12/12/2005	SNYDER LANG		Mechanical drawin			SNYDER	Marivic S. Ha		
		67	B	1160	CLO	Duct work for AC-1	12/9/2005	Luis Barrios, Jr	DDWA	12/12/2005	SNYDER LANG		The area (west of			SNYDER	Marivic S. Ha	2	
		66	A	1159	CLO	Exit Signage Requirements for Doors 6 & 7 @	12/9/2005	Luis Barrios, Jr	DDWA	12/13/2005	SNYDER LANG		Exit Signage for Door			SNYDER	Will Scott		